STREAMHOUSE

COMMUNITY REVITALIZATION PROJECT PLAN

Town Hall II

INTRODUCTIONS

 \circ Volunteer Board of Directors


Community Manager – Kaycie Lambright
Powerstone Property Management

Construction Manager - Conor Ross
Project Manager - Matt Nawabi
Ross Construction Management

OVERVIEW


- Town Hall I presented the Stream House revitalization project plan
- A survey was emailed to owners with addresses on record. The revitalization project plan has been customized based on the results of the survey.
- A second survey was sent to get owner feedback on funding options
- ° Tonight, we will go over all the options, budget, and voting results

WHY ARE WE HERE?





ROOF LEAK RELATED EXPENSES



CURRENT ROOF CONDITION

 \circ Poor – very poor

 \circ Well past useable life

 \circ Multiple roof systems

- Built-up Roofing Systems (hot mop roofs)
- \circ Torch down roofs
- Coatings on both (stop-gap measure)

CURRENT ROOF CONDITION

\circ Indicators of roof failure

- Coating delamination from ponding
- $\circ\ {\rm Crack}\ {\rm telegraphing}\ {\rm through}\ {\rm the}\ {\rm asphaltic}\ {\rm roofs}$
- $\circ\,$ Recent Maintenance (Antis Roofing and Waterproofing)
 - $\circ~$ All visible failures were addresses
 - New failures are already showing up
 - $\circ\,$ Frequency of failures is increasing as the oils degrade
- Ponding
 - Increases failures
 - Voids BUR warranty
 - $\circ\,$ Proposed roof is ponding resistant

MCCARTHY ROOFING ROLL ON COATING

• The following buildings were worked on by McCarthy Roofing. The Scope of Work was to apply roll on coating

• 2020

- 190 Singingwood #11,
- \circ 190 Singingwood #12
- $\circ 204$ Singingwood #2
- 5727 Stillwater #11
- 5846 Creekside #9
- ° 2021
 - 190 Singingwood #14
 - $\circ 178$ Singingwood #2



Coating Issues



Holes on coating

Coating Issues






Coating Issues







Coating Issues – Ponding Water









Inside Leak Examples at Stream House HOA

Previous Failure

Areas -Pipes



Old Leak Areas – New System Addresses Them Completely



Materials Being Used & Warranty

- $\circ~IB\,Roof\,Systems$ 60-mil PVC Roofing System
 - Extended 25-year Total Systems Warranty
 - Seams are welded with hot air, not an open flame.
 - PVC roofing is basically a modified pool liner, so any current ponding water is not an issue with this system and does not void the warranty.
 - All your weak points in your roofing system become your strong points with IB PVC.
 - Improved UV reflection



ROOF BIDS

Stream House Flat Roofs Bid Comparison										
VENDOR		Antis		Fontaine		Celoseal				
PRODUCT		Single-Ply		Single-Ply		Single-Ply				
Building Style	QTY	Cost per Building	Extended Cost	Cost per Building	Extended Cost	Cost per Building	Extended Cost			
А	6	\$22,603.69	\$135,622.14	\$24,577.00	\$147,462.00	\$23,975.00	\$143,850.00			
В	15	\$23,344.32	\$350,164.80	\$25,435.00	\$381,525.00	\$24,398.00	\$365,970.00			
С	11	\$38,560.92	\$424,170.12	\$41,755.00	\$459,305.00	\$39,973.00	\$439,703.00			
D	12	\$43,524.12	\$522,289.44	\$47,320.00	\$567,840.00	\$44,913.00	\$538,956.00			
E	5	\$46,169.23	\$230,846.15	\$50,142.00	\$250,710.00	\$47,899.00	\$239,495.00			
F	3	\$45,207.37	\$135,622.11	\$49,047.00	\$147,141.00	\$46,976.00	\$140,928.00			
BUILDINGS	52	Project Total	\$1,798,714.76	Project Total	\$1,953,983.00	Project Total	\$1,868,902.00			


ROOF SOLUTION BUDGET

ROOF BUDGET								
ltem		Amount	Notes					
Total Re-Roof Contra	act	\$1,868,902.00	Middle Bid					
Roof Contingency 15%		\$280,335.30	Estimated					
Abatement		\$50,000.00	Estimated					
Total		\$2,199,237.30						

ROOF SURVEY RESULTS

I agree that the flat roofs at Stream House are in need of replacement and want them included in the project plan. Adding this project could have a monthly cost to me of roughly \$115.15 per unit per month for 15 years

50 responses



Copy

ROOF STATUS: INCLUDED IN REVITALIZATION PROJECT

O2DECKS&BEAMS

DECKS ARE BEGINNING TO FAIL

CURRENT CONDITION OF DECKS

$\circ\ Ok$ to Poor

- $\circ~$ Decks rated "ok" need a maintenance coat
- Decks rated poor have (or will soon) fail
- $\circ~222$ total decks at Stream House (154 front and 68 rear)
 - 26 are rated "ok"
 - 196 are rated "poor"

• Maintenance

- Catches issues before they become major
- Keeps "ok" decks from becoming "poor" decks
- $\circ~$ Should be coated every 4 years










DECK BUDGET

REVISED DECK BUDGET

ltem		Amount	Notes	
Deck Repair		\$405,773.17	High Bid	
Worst Beams		\$15,000.00	Budget	
Deck Contingency	30%	\$126,231.95	Estimated	
Deck Inspection		\$5,779.21	Paid - Complete	
Total		\$552,784.33		


DECK & BEAM SURVEY RESULTS




DECK AND BEAM STATUS: INCLUDED IN REVITALIZATION PROJECT




CONCRETE PATIO SURVEY RESULTS




CONCRETE PATIO STATUS: NOT INCLUDED IN REVITALIZATION PROJECT

















CORING REPORT

Core#	Location	AC (in)	AB(in)	Notes/Subgrade
				Firm subgrade, River Rock AB, core taken on
1	5715 Stillwater, Unit 1	3.75	6	Old AC
	5727 S. Stillwater, Unit			
2	12	3.1	6	Firm subgrade
	5739 E. Stillwater, Unit			
3	2	3.1	6	Firm subgrade, core taken on newer AC
	152 N. Singingwood,			
4	Unit 4	3.8	6	Firm subgrade, core taken at parking stalls
	166 N. Singingwood,			
5	Unit 1	3.4	6	Firm subgrade, core taken on old and new AC
	190 N. Singingwood,			
6	Unit 13	3.5	6	Firmsubgrade
	222 N. Singingwood,			
7	Unit 1	2	6	Firmsubgrade
8	5845 Creekside, Unit 27	3.25	6	Firm subgrade
9	5845 Creekside, Unit 29	3.5	6	Firm subgrade
				Firm subgrade, fabric encountered 1" below
10	5744 Creekside, Unit 55	5.5	6	AC
				Firm subgrade, fabric encountered 1.25"
11	5744 Creekside, Unit 43	5.25	6	belowAC
12	5744 Creekside, Unit 30	6	6	Firm subgrade
				Firm subgrade, fabric encountered 0.75"
13	5744 Creekside, Unit 5	3.25	6	below AC
				Firm subgrade, fabric encountered 1.5" below
14	5744 Creekside, Unit 36	4	6	AC


ASPHALT BIDS

Stream House Asphalt Bid Comparison						
VENDOR	CITY SERVICE		JB BOSTICK		QUICKEL	
PRODUCT	ASPHALT		ASPHALT		ASPHALT	
STREETS	1.5"+ mill & Overlay with Forta-Fi	Option 1 Full Remove & Replace	1.5"+ mill & Overlay with Forta-Fi	Option 1 Full Remove & Replace	1.5"+ mill & Overlay with Forta-Fi	Option 1 Full Remove & Replace
SUBTOTAL	\$ 133,000.00	\$ 198,900.00	\$ 117,609.00	\$ 183,496.00	\$ 163,990.00	\$ 203,990.00
SEAL COAT	\$ 26,250.00	\$ 26,250.00	\$ 11,812.00	\$ 11,812.00	INCLUDED	INCLUDED
ASPHALT TOTAL	\$ 159,250.00	\$ 225,150.00	\$ 129,421.00	\$ 195,308.00	\$ 163,990.00	\$ 203,990.00

ASPHALT BUDGET

ASPHALT				
Item		Amount	Notes	
Total Asphalt (Remove and Replace)		\$225,150.00	Middle Bid	
Asphalt Contingency	20%	\$45,030.00	Estimated	
Coring		\$2,416.00	Paid – Complete	
Total Asphalt		\$272,596.00		

ASPHALT SURVEY RESULTS



ASPHALT STATUS: INCLUDED IN REVITALIZATION PROJECT



05 CONCRETE WALKWAYS

• The walkways within the community have shifted over time, resulting in trip hazards

- \circ Scope of work
 - Trip hazard grinding
 - Crack repair
 - Remove and replace

CONCRETE WALKWAYS




CONCRETE WALKWAYS BUDGET

CONCRETE WALKWAYS

Item	Amount
Trip Hazard Grinding	\$7,525.00
Crack Repair	\$1,360.00
Concrete – Remove & Replace	\$23,810.00
Total Concrete Walkway Repair Cost	\$32,695.00

CONCRETE WALKWAYS SURVEY RESULTS



CONCRETE WALKWAY STATUS: INCLUDED IN REVITALIZATION PROJECT


06 STREAM CLEANING & MAINTENANCE

06 STREAM CLEANING & MAINTENANCE

 Deferred maintenance of draining and cleaning the streams and preventative maintenance on the pumps has caused costly repairs that the association cannot keep up with.

• Lake Maintenance Cost - \$28,750

STREAM CLEANING & MAINTENANCE SURVEY RESULTS



STREAM CLEANING & MAINTENANCE STATUS: INCLUDED IN REVITALIZATION PROJECT




07 FINANCIAL DEFICIT REIMBURSEMENT

 Stream House has been borrowing money from the Reserves for years to cover Operating Expenses.

 \circ Reserves need to be reimbursed


• Deficit (reimbursement amount) - \$60,000

FINANCIAL DEFICIT SURVEY RESULTS



FINANCIAL DEFICIT STATUS: INCLUDED IN REVITALIZATION PROJECT

PROJECT BUDGET – APPROVED STREAM HOUSE REVITALIZATION PLAN



PROJECT BUDGET

REVITALIZATION PROJECT PLAN BUDGET


Total Re-Roof Cost	\$2,199.237.30
Total Asphalt	\$272,596.00
Total Worst Decks Cost	\$552,784.33
Total Concrete Walkways Cost	\$32,695.00
Subtotal (All Projects)	\$2,605,715.38
Contingency & Project Mgmt., Misc.	\$647,025.90
Project Total	\$3,252,741.28
Lake Maintenance	\$28,750.00
Deficit	\$60,000.00
Project Total (Including Deficit)	\$3,341,491.28

FUNDING OPTIONS - (INCLUDED IN SURVEY 2)

• Amount: \$3,341,500.00

- Term:
 - Up to twelve (12) months, the loan functions as a non-revolving line of credit, then converts to one of the following
 - $\circ\,$ 15-Years: Estimated \$168.84 per unit per month for 15 Years
 - $\circ\,$ 10-Years: Estimated \$222.84 per unit per month for 10 Years.
 - $\circ\,$ 5-Years: Estimated \$389.42 per unit per month for 5 Years.
- Interest Rate: 5.75%
- $\circ\,$ Fees: Commitment Fee of .25% (\$8,354.00), documentation fee \$500.00
- Prepayment Penalty: 5%, 4%, 3%, 2%, 1% on term portion (only in effect if the association re-finances with another lender)

FUNDING SURVEY RESULTS



5-year term loan - estimated \$389.42
per unit per month for 5 years
10-year term loan - estimated \$222.84
per unit per month for 10 years
😑 15-year term Ioan - estimated \$168.84
per unit per month for 15 years

Terms	Votes	Percentage	
5 Year	5	8.9%	
10 Year	11	19.6%	
15 Year	40	71.4%	
Total Votes	56	100%	

ALTERNATIVE TO LOAN

- Reserves remain underfunded, possibly delaying repairs for other items
- Possibly annual increases up to 20% year + 5% per year special assessment.
- More interior damage, resulting in redundant, costly repairs
- Increased insurance premiums

VOTING REQUIREMENTS

- To approve an assessment, more than half of all the units must return a ballot, and more than half of the votes that are cast must be in favor of the assessment.
- Stream House has 166 units, so that means at least 84 units must return ballot to establish quorum needed just to be able to open and count ballots. To approve the measure, a majority of received ballots (once quorum is met) must be "yes".

IT'S ALL UP TO YOU ~ <u>EACH</u> OF YOU!

• <u>We need your "Yes" vote!</u>

• We also need your neighbors' "YES" votes as well for this to pass

• Ballots will arrive at your home

WE NEED YOUR HELP & SUPPORT TO SOLVE THIS AS A COMMUNITY!

